


Research at FHR





Lime treatment of levee cover





Updated Sigmaplan




Why

- Qualified clay not always (locally) available
- Strengthening transitions (along roads, around encroachments) on the landward slope
- Levees resistant to (continuous) overflow/(wave) overtopping
 - Increasing acceptable overtopping discharge (reducing requested crest level)
 - Allowing (limited) overflow (extending life time)
 - Increasing protection level of system











D1

75/25

1

niets

Teen

Afdek + 75/25

??

Construction





Section B: local soil treated + cover + 75/25

04/09/2020

15/03/2021



Section C: Local soil treated + 75/25

04/09/2020

15/03/2021





Survey

- Development of the vegetation cover
- Permeability: double ring & lab
- Erosivity: JET
- Resistance to penetration: PANDA
- In situ overflow experiments by 2024...






Overflow experiments by 2024...











Lesser quality clay EC2 Section 1A and 1B Lesser quality clay EC2 Sections 2A and 2B Good quality clay EC1 Sections 3A and 3B

Sections 1B, 2A and 3A to be tested WITHOUT OBJECT (the section of 4m wide to be shifted over 1,5 m towards transition zone, see arrows)

Deltares



Construction






Construction











Wave overtopping experiments










First results











Thank you

patrik.peeters@mow.vlaanderen.be

